
Latest information

Always use the most recent firmware version for this unit. For information about the latest firmware, visit the TEAC Global Site (<http://teac-global.com/>).

New functions

ML-32D / ML-16D Dante firmware

V1.2.0 additions

SMPTE2110-30 has been supported.
Dante Domain Manager (DDM) v1.1 or later is required to use SMPTE 2110-30 audio.

V1.1.0 additions

- Dante Domain Manager is now supported.
In V1.1.0, the Dante module Software Version will be 1.1.0, and the firmware Version will be 1.1.0.
Software Version: 1.1.0
Firmware Version: 1.1.0